Release Information

Anybus Wireless Access Point IP30/67 with Mesh

This release contains the following firmware files:

FW file	Firmware Version	Bootloader Version	Comment
AWB514x-1.5.6.img	V1.5.6.2	V1.3	

Release Information
Anybus Wireless Access Point IP30/67 with Mesh

Reason for release:

- Profinet compatibility fix.

Compatibility:

This release works on Anybus Wireless Point IP30 and Anybus Wireless Access Point IP67 with Mesh.

Firmware update - Instructions

See the Anybus Industrial WLAN Access Point manual (document SCM-1202-155) section 5.13 for Firmware Update instructions. The User Manual can be downloaded from www.anybus.com/support.

Release Information

Anybus Wireless Access Point IP30/67 with Mesh

All changes:

1.5.6.2

Type	Summary
Fix	Fix for Profinet PN-DCP issue

1.5.6

Type	Summary
Fix	Fix Israel regulatory domain for outdoor use

1.5.5

Type	Summary
Fix	Fix Singapore regulatory domain selection

1.5.4

Type	Summary
Fix	Fix firmware update validation procedure.

1.5.3

Type	Summary
Fix	Fix for WDS issue