

ChangeLog - ABC3113

Table of Contents

ABC3113 - 1.01.01.....	1
ABC3113 - 1.00.01.....	1

ABC3113 - 1.01.01

First public release

Category	Description	Comment
Bug fix	Unmapped input bits have random values.	Fixed an issue that caused unmapped input bits in mapped input bytes to have random values. Now they are fixed at 0.
Bug fix	Failed to init Ectm with large configurations	Increase maximum network size for the EtherCAT MainDevice. Networks containing large subordinates with many PDOs should now be supported.
Bug fix	Scanning of ABCC40 first in line fails.	Fixed a bug that caused the EtherCAT Main device to issue SDO requests before the subordinates had completed their transition to PRE_OP. This caused some subordinates to show up without any CoE data during a scan.

ABC3113 - 1.00.01

Initial internal release EtherCAT MainDevice - PROFINET

Category	Description	Comment
New Feature	EtherCAT MainDevice Scanning FW	Initial support of EtherCAT MainDevice based on scanning functionality
New Feature	EtherCAT MainDevice Scanning GUI	Initial support of EtherCAT MainDevice based on scanning user interface